

Work Order ID 149386

July 22, 2016 3:09:39 PM

149386

Page 1

Item ID: D3562-041 Accept *N900040100* Setup Start *NS1*

Revision ID:

Item Name: Step Weldment Stop *NS2*

Start Date: 7/14/2016 Start Qty: 4.00 *4*

Required Date: 7/22/2016 Req'd Qty: 4.00 *4*

Reference:

Cust Item ID:

Customer:

Approvals: Process Plan: SUA Date: 7/25/16 Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start *NR1*

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3562	G

100 0.00

100 Large Fab 0.44

Memo

1-Cut D2622 extrusion as per Dwg D3562

2-Deburr and bevel ends for welding

110 0.00

110 QC - Inspect dimensions to drawing 0.00

QC

Quality Control

Memo

120 0.00

120 Chemical Conversion Coat per QSI005 4.1 0.09

HandFinish

Hand Finishing

Memo

AMOD
DG

4 16-10-18

② 16-10-19 DAS 9 9-89

④ 2016/10/20 BEB

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☒

Work Order: <u>149386</u> Part No. <u>D3562-041</u> NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval DAS 9 9-89 16-10-19		
Description Work Order Deviation				Disposition				Completed By DAS 10 9-89	
Change to QCS				 				Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐		
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____					
Misidentified ☐	Past Due ☐						

Work Order ID 149386

July 22, 2016 3:09:39 PM

149386

Page 2

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Step Weldment
Start Date: 7/14/2016 Start Qty: 4.00 ***4*** Cust Item ID:
Required Date: 7/22/2016 Req'd Qty: 4.00 ***4*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	QC7-Inspect Chemical Conversion Coat	0.00							
130									
QC	Memo	0.01							
Quality Control									

140		0.00							
140	Small Fab								
Small Fab	Memo	0.89							
Small Fab	1- Transfer drill Rivet holes as per dwg D3562.								
	2-Touch-up rivet holes with alodine as per dwg d3562								
	3-Rivet legs using Scotch-Weld as per dwg D3562.								
	*****Ensure to wipe off any excess magnobond *****								

A/R Scotch-Weld DP460

Batch: 135579
EXP DATE: 9/17

4 OCT 25 2016

DAS
24
9-89

4 C 16-10-27

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

July 22, 2016 3:09:39 PM

Page 3

[illegible]

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	Bending ☐	Set-up. ☐	Folio/Program ☐	Outside Dimensions ☐
LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
				Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
				Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
				Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
				Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
				Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
				Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
				Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
				OTHER : _____			

Work Order ID 149386

July 25, 2016 1:32:21 PM

149386

Page 4

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Step Weldment
Start Date: 7/14/2016 Start Qty: 4.00 ***4*** Cust Item ID:
Required Date: 7/22/2016 Req'd Qty: 4.00 ***4*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
180 *180* QC Quality Control	QC5- Inspect part completeness to step on W/O Memo	0.00 0.01				<u>4</u>			DAS 38 9-89 OCT 31 2016
190 *190* HandFinish Hand Finishing	Chemical Conversion Coat per QSI005 4.1 Memo	0.00 0.17				<u>(x4)</u>	<u>6</u>		2016/10/31 BEB
201 *201* SprayPaint Spray Painting	Spray Painting per QSI005 4.2 Memo PRIME AS PER QSI 005 PRIME BATCH <u>135654</u> PAINT AS PER QSI 005 DRAB GREEN BATCH <u>135932</u>	0.00 0.00				<u>4</u>			DAS 41 9-89 16-11-4

July 25, 2016 1:32:21 PM

Page 5

4X _____ 16/11/11 _____ DAS 36 9-82

Work Order ID 149386

July 25, 2016 1:32:21 PM

149386

Page 6

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Step Weldment
 Start Date: 7/14/2016 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 7/22/2016 Req'd Qty: 4.00 ***4*** Customer:
 Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
230	Identify as per dwg & Stock Location: <i>w/o</i>	0.00							
230									
Packaging	Memo <i>1508/9</i>	0.01				<i>4x</i>			<i>16/11/14</i>
Packaging									
240	QC21- Final Inspection - Work Order Release	0.00							
240									
QC	Memo	0.07							
Quality Control									

DAS
21
9-89

NOV 14 2016

dm 16/11/14

Picklist Print

July 22, 2016 3:09:39 PM

Page 1

Work Order ID: 149386

149386

Parent Item: D3562-041

D3562-041

Parent Item Name: Step Weldment

Start Date: 7/14/2016

Required Date: 7/22/2016

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:A New Issue 06-11-09 JLM
 IPP rev B ECN 987 07.10.09 EC verified by: DD
 IPP Rev:C ECN1048 07-12-18 DD verified by:ec
 IPP Rev:D 08-07-28 add chemical conversion coat DD verf:EC IPP REV:E
 13.06.03 PER DWG REV.F DD VERF:JLM IPP REV:F 16.06.23
 AS PER DWG REV.G DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

MS20600-AD4W4

Purchased

No

Each

1,544.000

128

MS20600-AD4W4

Rivets

Location

Loc Qty

Loc Code

CCK005

1270

M133990

770

M134955

500

LG

74

M133694

74

ST308

140

M133990

140

WA003

60

M133990

60

D2622-120C

Manufactured

No

100

Each

117.7360

1

4

D2622-120C

Step Extrusion

Location

Loc Qty

Loc Code

WA003

97.736

130161

0.236

141814

97.5

WA004

20

140539

20

B135442

**

130

16-10-26

**

4

16-10-18

141814 → 1x

150070 → 3x

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

July 22, 2016 3:09:39 PM

Page 2

Work Order ID: 149386

149386

Parent Item: D3562-041

D3562-041

Parent Item Name: Step Weldment

Start Date: 7/14/2016

Required Date: 7/22/2016

Start Qty: 4.00

Required Qty: 4.00

D2734

Manufactured No

140

Each

55.0000

2

8

D2734

Step End Plate

**

OCT 31 2016

DAS
24
9-89

Location

Loc Qty

Loc Code

WA003

55

145802

55

3151475 → 8

D3560-041

Manufactured No

140

Each

1.0000

1

4

D3560-041

Arm Weldment

**

4 C 16-10-25

Location

Loc Qty

Loc Code

WA003

1

124288

1

~~149338~~
149374

D3560-043

Manufactured No

140

Each

0.0000

1

4

D3560-043

Arm Weldment

**

4 C 16-10-25
149338 →

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE


QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER :					

8 7 6 5 4 3 2 1

ITEM	QTY -041	P/N	DESCRIPTION
	X	D3562-041	LH STEP ASSEMBLY
1	1	D3560-041	ARM WELDMENT
2	1	D3560-043	ARM WELDMENT
3	1	D3562-1	STEP ASSEMBLY
4	32	MS20600AD4W4	RIVET, BLIND



MEASURED BEFORE END CAPS WELDED IN PLACE


RELEASED

2016 JUN 22
ECN K-66J

SH 7/25/16 149386

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH:
 - i) POWDER COAT ASSEMBLY:
GLOSS WHITE (4.3.5.1) OR
GREY SANDTEX (4.3.5.6) OR
BLACK SANDTEX (4.3.5.7) OR
GREEN SANDTEX (4.3.5.8) PER DART QSI 005 4.3
 - ii) BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 8.80 lbs
- 8) INSTALL ARM WELDMENTS WITH A LAYER OF SCOTCH-WELD DP460 BETWEEN THE ARM WELDMENT AND STEP EXTRUSION. FILL ANY TOOLING HOLES WITH SCOTCH-WELD DP460. CLEAN OFF EXCESS BEFORE POWDER COATING.
- 9) TRANSFER DRILL #30 DEBURR & TOUCH UP HOLES WITH CHEMICAL CONVERSION COAT BEFORE RIVETING




D3562-041 LH STEP ASSEMBLY

REV.	DESCRIPTION	BY	DATE
G	MS20600AD4W4 WAS MS20600AD4W5. REF. PAR16-S17.	MB	16.04.21
F	REVISED NOTE 8 TO REMOVE MAGNOBOND. REPLACE WITH SCOTCH-WELD DP460, REF. PAR12-224. ADDED NOTE 9 AND SHEET 2	DW	13.05.15
E	ADD QTY(2) TO D2734 END PLATE ON D3562-042	PH	08.01.11
D	REMOVE D2808 SPACER NOTE; REDRAW IN SOLIDWORKS	DC	07.11.18
C	NOW MAGNOBOND, ADD D2808. REMOVE 4 RIVETS	CP	07.08.19
B	ARMS NOW RIVETED TO STEP	CP	07.01.15
A	NEW ISSUE	CP	06.09.26
DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	MB		
CHECKED	ML	DRAWING NO. D3562	REV. G
MFG. APPR.	DD		SHEET 1 OF 3
APPROVED	WM	TITLE	SCALE
DE APPR.	DS	STEP ASSEMBLY	NTS
DATE	16.04.21	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

APPROVED


8 7 6 5 4 3 2 1

ITEM	QTY -042	P/N	DESCRIPTION
	X	D3562-042	RH STEP WELDMENT
1	1	D3560-042	ARM WELDMENT
2	1	D3560-044	ARM WELDMENT
3	1	D3562-1	STEP ASSEMBLY
4	32	MS20600AD4W4	RIVET, BLIND



NOTES:

- 1) MATERIAL: N/A
- 2) FINISH:
 - i) POWDER COAT ASSEMBLY:
 - GLOSS WHITE (4.3.5.1) OR
 - GREY SANDETEX (4.3.5.6) OR
 - BLACK SANDETEX (4.3.5.7) OR
 - GREEN SANDETEX (4.3.5.8) PER DART QSI 005 4.3
 - ii) BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 8.80 lbs
- 8) INSTALL ARM WELDMENTS WITH A LAYER OF SCOTCH-WELD DP460 BETWEEN THE ARM WELDMENT AND STEP EXTRUSION. FILL ANY TOOLING HOLES WITH SCOTCH-WELD DP460. CLEAN OFF EXCESS BEFORE POWDER COATING.
- 9) TRANSFER DRILL #30 DEBURR & TOUCH UP HOLES WITH CHEMICAL CONVERSION COAT BEFORE RIVETING




D3562-042 RH STEP ASSEMBLY

RELEASED


2016 JUN 22 *ap*

APPROVED	DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	DRAWN	MB		
	CHECKED	ML	DRAWING NO.	REV. G
	MFG. APPR.	DD	D3562	SHEET 2 OF 3
	APPROVED	WM	TITLE	SCALE
	DE APPR.	DS	STEP ASSEMBLY	NTS
DATE		16.04.21	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

ITEM	QTY -1	P/N	DESCRIPTION
	X	D3562-1	STEP ASSEMBLY
1	A/R	D2622-XXX	STEP EXTRUSION
2	2	D2734	END PLATE



D3562-1 STEP ASSEMBLY



DETAIL A D8-2
TYP BOTH ENDS
SCALE 1.5X

NOTES:

- 1) MATERIAL: MAKE FROM D2622 EXTRUSION
- 2) FINISH: CHEMICAL CONVERSION COAT STEP EXTRUSION
PER DART QSI 005 4.1 BEFORE ASSEMBLY
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 6.68 lbs
- 8) WELDING: ALL WELDS SHALL BE 100% VISUALLY INSPECTED
BY A QUALIFIED INSPECTOR PER DART QSI 004

RELEASED

2016 JUN 22 *q*

APPROVED	DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	DRAWN	MB		
	CHECKED	ML	DRAWING NO. D3562	REV. G
	MFG. APPR.	DD		SHEET 3 OF 3
	APPROVED	WM	TITLE	SCALE
	DE APPR.	DS	STEP ASSEMBLY	NTS
	DATE	16.04.21	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	